

N^o 11299

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-15-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 100

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR HOW

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

BirP

Inspector for City

FILED AT ENGINEER'S OFFICE _____

CURB

REMARKS _____

Nº 11299

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 14, 20

RECEIVED OF Don WALKINS FEE OF \$ 10

FOR WHICH PERMISSION IS GRANTED H + W Contractors

REPAIR TO TAP for sanitary SEWER ON THE North S
CUTOFF

OF Lincoln Way East AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 127 (Grand Mill) (HOUSE NO. 100)

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H + W

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.