

Nº 11300

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-3-01

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. 1708

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_


SIZE OF PIPE USED —

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR B. M. W. Wrecking

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. M. W.  
Inspector for City

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

Nº 11300

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/14, 2015  
RECEIVED OF Buckeye Wrecking FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

REPAIR  
TO TAP Sanborn SEWER ON THE West S  
CUTOFF East of 1st AVE.  
OF 10004 ST. TYPE OF STREET South St  
THE PREMISES BEING LOT NO. \_\_\_\_\_, HOUSE NO. 1708

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE  
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Buckeye Wrecking

**Note: This permit covers work outside of building only. Any work inside  
walls of building is subject to Massillon Board of Health regulations.**