N° 11303

REMARKS _

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	DISTANCE FROM FIRST MANHOLE DOWN STREAM DOWN STREAM TO DITCH AT		
WAS LATERAL AT CURB? 25	NAME OF CONTRACTOR Marieta Ghe.		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
SIGNED Del All All All All All All All All All A	FILED AT ENGINEER'S OFFICE		

Nº 11303

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

208:5

	MASSILLON, OHIO,	6/aL/,20_
RECEIVED OF MAJALLET		_ FEE OF \$
FOR WHICH PERMISSION IS GRANTED 1	usa Horres	
	ER ON THE	let
OF WOLLD CH CH ST. TYPE	OF STREET	do on
THE PREMISES BEING LOT NO	/ , HOUSE NO	118
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1 DEPARTMENT OF PUBLIC SERVICE.	971 DULY PASSED BY THE CITY COUN	ICIL, AND RULES OF THE
NAME OF CONTRACTOR MULICIAL ACTUAL AC		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.