## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-25-01	IF SO, HOW AND LOCATION FROM		
HOUSE NO. 2366	FIRST MANHOLE DOWN STREAM		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? 15	. 1 1 0		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Molecular Engl		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	8 perp		
	SIAGS 5-1		
•	450 138'		
	450 100		
SIGNED Bill	/S D&E/		
Inspector for City			

REMARKS \_\_\_\_\_

Nº 11304

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	<u> </u>
RECEIVED OF Mala	<u> La</u>	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Lidgian hol	Horne
	VER ON THE	ander
OF AME.	PE OF STREET(	anybalt
THE PREMISES BEING LOT NO	3, HOUSE NO	. 1360
	Section 1988	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19	3.1971 DULY PASSED BY THE C	TY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.		i de la companya de l
NAME OF CONTRACTOR	The state of the s	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.