

Nº 11312

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-7-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1360

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Rentgen Co.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Birdman

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11312

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 6, 2001, 20

RECEIVED OF Efficient Homes FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Bontreger Excavating

REPAIR TO TAP top sanitary SEWER ON THE East S
CUTOFF

OF Lonedale Street AVE. ST. TYPE OF STREET concrete

THE PREMISES BEING LOT NO. 11033 (14), HOUSE NO. 1310

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bontreger

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.