

Nº 11313

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-8-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1340

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Bontrogen Bros.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

B. J. P.

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11313

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 6, 2001

RECEIVED OF Efficient Homes FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Bontager Excavating

REPAIR TO TAP tap sanitary SEWER ON THE East S
CUTOFF

OF Lowdale St NW AVE. ST. TYPE OF STREET concrete

THE PREMISES BEING LOT NO. 16131 (15), HOUSE NO. 1340

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bontager

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.