N^{0} 11319

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	8/16/01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO.	1035				
SIZE OF PIPE USED	6*				
WAS LATERAL AT CURB?	yes				
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
Signed M M Signed Filed at Engineer's Office					
REMARKS					

Nº 11319

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

<i>]</i> !	, MASSILLON, OHIO,	7/1.60
RECEIVED OF	rughell Con	LO FEE OF \$ 5
/ 	qualicel	<u> </u>
REPAIR James	sewer on the	West
of Scarfward	AVE. PEOF STREET	replace
THE PREMISES BEING LOT NO	01587 , HOUS	SE NO
	/	
WORK TO BE DONE IN ACCORDANCE WITH DEPARTMENT OF PUBLIC SERVICE.	HORDINANCE NO. 19.1971 DULY PASSED BY	YTHE CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	qualiel	en e
	1	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.