## $N^{0}$ 11321

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	8/16/01	IF SO, HOW AND LOCATION FROM 129'	
HOUSE NO.	1055		
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	yes	Grabill	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
Scottwood Place  12' from S corner  18'  8'  SIGNED MM Inspector for City  FILED AT ENGINEER'S OFFICE			
0	парескої ког Сіку		

## Nº 11321

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

/· MA	SSILLON, OHIO, 7//202
RECEIVED OF Shidall	Condo (chizeedes 5
FOR WHICH PERMISSION IS GRANTED	red was
TO TAP SEWER ON	ITHE WILLET
OF JULYUNIA PRITYPE OF	STREET dopdat
•	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971   DEPARTMENT OF PUBLIC SERVICE.	DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR GUSLINI	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.