


Nº 11324

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/16/01 IF SO, HOW AND LOCATION FROM 129'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1085
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH yes
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11324

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/1/82

RECEIVED OF

Springhill Condo (Ch 1202)

FREE OF \$

50

FOR WHICH PERMISSION IS GRANTED

General

REPAIR
TO TAP
CUTOFF

Sanitary

SEWER ON THE

West

SI

OF

Scotwood

AVE.

ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

00587

HOUSE NO.

1085

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

General

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**