

N^o 11328

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-19-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2310

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR M. J. White Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. J. Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11328

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/18₂₀

RECEIVED OF

Mulawite

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Sandberg

SEWER ON THE

East

SI

OF

Mount Union Ave

AVE. E

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

15982

, HOUSE NO.

2310

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Homes by Ashley

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.