## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED <u>9-20-01</u>	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 4553-4555	DISTANCE FROM FIRST MANHOLE			
SIZE OF PIPE USED6"	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?				
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	N 22° - 13'			
SIGNED Inspector for City	12° 1 ) 3 par la			

 $N^{\underline{0}} \quad \boxed{11339}$ 

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

	MASSILLON,	OHIO,	8/,207
RECEIVED OF	<del>/\\\</del>		FEE OF \$
FOR WHICH PERMISSION IS GRANTED			
TO TAP	SEWER ON THE		Jan Za
OF	AVE, SY TYPE OF STREET _		aughert
THE PREMISES BEING LOT NO.	16/47	_, HOUSE NO	4153-41
* * * * * * * * * * * * * * * * * * * *			
WORK TO BE DONE IN ACCORDANCE V	VITH ORDINANCE NO. 19.1971 DULÝ PAS	SED BY THE CIT	TY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	// /		
NAME OF CONTRACTOR	Glick		_
× 71	and the second s		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.