## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-20-8/ HOUSE NO. 424	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 445	NAME OF CONTRACTOR Cather Colored Cinx
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	MILDING SERVED.
SIGNED Bill City	FILED AT ENGINEER'S OFFICE
REMARKS	

 $N^{\circ}$  11348

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Cart days	MASSILLON, OHIO, -		9/,200
RECEIVED OF			FEE OF \$	/_1
FOR WHICH PERMISSION IS GE	RANTED			
REPAIR TO TAP	A LA SEW	ÉR ON THE	Madetal	
CUTOFF	7 7/	) E OF STREET	,	
OF	الإلامرية التي المراجع التي التي التي التي التي التي التي التي		1	3
THE PREMISES BEING LOT NO.	4153	, HOUSI	E NO	<i>Y</i> -
	į		,	<i>!</i>
WORK TO BE DONE IN ACCORE	DANCE WITH ORDINANCE NO. 19	.1971 DULY PASSED BY	THE CITY COUNCIL, AND RU	JLES OF THE
DEPARTMENT OF PUBLIC SERV	/ICE. / ) ·			
ULLE OF COLUTE LOTOR	MA FA	hill		
NAME OF CONTRACTOR		~ ( · · · · · · · · · · · · · · · · · ·		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.