## $N^{0}$ 11349

REMARKS .....

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	9/19/01	_ IF SO, HOW AND LOCATION FROM 1997	198′	
HOUSE NO.	1820	FIRST MANHOLE DOWN STREAM		
SIZE OF PIPE USED	6 <b>*</b>	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH		
WAS ATTACHED TO MAIN	yes	Jim Burke Ex NAME OF CONTRACTOR	<b>(C.</b>	
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF	Rayco 1820 Prospect DR SE  1820 Prospect DR SE  1821 Prospect DR SE  1821 Prospect DR SE  1821 Prospect DR SE  1822 Prospect DR SE  1824 Prospection chamber  1825 Prospection chamber  1825 Prospection chamber  1826 Prospection chamber  1826 Prospection chamber  1826 Prospection chamber  1827 Prospection chamber  1828 Prospection chamber  1829 Prospection chamber  1820 Prospection	r 123' fran se corner of b running east	
SIGNED Y	Inspector for City	FILED AT ENGINEER'S OFFICE		

## Nº 11349

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON,	OHIO,	9/17,20_
RECEIVED OF	Wedgen		FEE OF \$
FOR WHICH PERMISSION IS GRANTED			
TO TAP CUTOFF	SEWER ON THE		with the
OF	ST. TYPE OF STREET _	a ax	
THE PREMISES BEING LOT NO.	Pro1569	, HOUSE NO	1 1/820
	WITH ORDINANCE NO. 19.1971 DULY PASS		NCIL, AND RULES OF THE
	/		
2.00	/ 1		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.