FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-20-0	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? VES	Λ Λ
WAS ATTACHED TO MAIN 7/3 5	NAME OF CONTRACTOR FISHER CLE
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BI	UILDING SERVED.
	3'\22 17'\(\)
SIGNED	FILED AT ENGINEER'S OFFICE
REMARKS	

N^{0} 11351

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, OHIO, —	9/. 7, 20
FOR WHICH PERMISSION IS GRANTED		
REPAIR TO TAP CUTOFF	SEWER ON THE	Anta
of feddle theeld the	AVE/C ST/TYPE OF STREET	andrell
THE PREMISES BEING LOT NO.	, House	NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE DEPARTMENT OF PUBLIC SERVICE.	E NO. 19.1971 DULY PASSED BY TI	HE CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	ended	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.