


Nº 11355

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-27-01 IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 574'
HOUSE NO. 1565
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Melvin E. Egan
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Egan FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11355

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Sept 26 1920

RECEIVED OF Matavile Exc. FEE OF \$ 01

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Sanitary SEWER ON THE South SIDE
CUTOFF
OF Gilman St AVE.
ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15586, HOUSE NO. 1565

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Matavile Exc.

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**