REMARKS .....

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	10/03/01	. IF SO, HOW AND LOCATION FROM 119'	
HOUSE NO.	1347	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	6 <b>"</b>	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED 119'			
		6 Jan 19	
		4 from w corner	
	-	Tylers Mill Lone	
SIGNED ON W	r flig	FILED AT ENGINEER'S OFFICE	
1.0	Irispector for City	•	

## Nº 11359

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, $9/20$
RECEIVED OF A JUNG ALL CALLETONS 57
FOR WHICH PERMISSION IS GRANTED
TO TAP SANITALLY SEWER ON THE STUTA
OF Jally All Ja ST. THE OF STREET UN ALLALA
THE PREMISES BEING LOT NO
/ /
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR ALABALLE

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.