

Nº 11379

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-17-01 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____


HOUSE NO. 1630-32

SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Malvarde Eng.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED BioP Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

N^o 11379

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/15

RECEIVED OF Malawite FEE OF \$ 57

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP CUTOFF Sanitary SEWER ON THE East S

OF Edgewood Blvd 7th AVE ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 06647, HOUSE NO. 1630

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malawite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.