

Nº 11382

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 10/23/01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

120

HOUSE NO. 117

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Beaver

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11382

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/18 2010

RECEIVED OF Beaman

FEE OF \$ 100

FOR WHICH PERMISSION IS GRANTED Beaver Excavating

REPAIR
TO TAP
CUTOFF

SEWER ON THE North S

OF Cherry Rd N

AVE.

ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 1

6 - area site

HOUSE NO. 117

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beaman

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**