N^0 11386

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED //-/G-01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO3 698	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 455	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Called (a) reason.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BL	JILDING SERVED. 36 Crear Tire 767 From CURB CURB
SIGNED Bio Pinspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 11386

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER ,

	MASSILLON, OHIO,	10/20/2
RECEIVED OF	Catheril	FEE OF \$
OR WHICH PERMISSION IS GRANTED		
REPAIR ALCO	A MASEWER ON THE	Part
CUTOFF Stud St	AVE. ST. TYPE OF STREET	acchiet
HE PREMISES BEING LOT NO.	16. 11 11 11 11 11 11 11 11 11 11 11 11 11	1 2
LETTINGED BEING EST NO.		•
ORK TO BE DONE IN ACCORDANCE WIT	H ORDINANCE NO. 19.1971 DULY PASSED BY THE CI	TY COUNCIL, AND RULES OF THE
EPARTMENT OF PUBLIC SERVICE.	1	
AME OF CONTRACTOR	LATIALLY	<u> </u>

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.