## Nº 11392

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-13-01 HOUSE NO. 4540	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Johns Exter				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
	8 pps 19' 19' 19' 19' 19' 19' 19' 19' 19' 19'				
SIGNED RUM /Inspector for City	FILED AT ENGINEER'S OFFICE				

## Nº 11392

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	$\cap$ $\wedge$	₩ MASSILLON, (	OHIO,	//-, 20/
RECEIVED OF	John:	o Excusa	Luz	FEE OF \$
FOR WHICH PERMISSION	I IS GRANTED			······································
REPAIR TO TAP	Landon,	SEWER ON THE	Art	ad
CUTOFF (1)	1."	, AVE ST-TYPE OF STREET		and ald
THE PREMISES BEING LO			HOUSE NO.	1417/3-4/5
WORK TO BE DONE IN AC	CCORDANCE WITH ORDINAN	CE NO. 19.1971 DULY PASS	ED BY THE CITY CC	UNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC	$\langle \langle \langle \langle \rangle \rangle \rangle \rangle / \langle \langle \rangle \rangle$	he. 1. 2		
NAME OF CONTRACTOR		1st 2 ory		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.