

N^o 11415

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-22-02 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 939
SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Holderbaum
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

No Repair needed out side of House.

SIGNED *Jeffrey M. King* FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11415

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/18, 20

RECEIVED OF Holcomb FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Holcomb

REPAIR TO TAP Sanitary SEWER ON THE South S
CUTOFF

OF Tramont Ave. (AVE.) ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 3138, HOUSE NO. 939

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Holcomb

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**