

Nº 11422

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1/28/02

HOUSE NO. 2240

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 84'

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

NAME OF CONTRACTOR Malivite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Jeffrey M. King Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

N^o 11422

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

1-25-20

RECEIVED OF _____

M. L. L. Co.

FEE OF \$ _____

50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Repaired at 159th

SEWER ON THE _____

East

S

OF _____

AVE.

ST.-TYPE OF STREET _____

Albion

THE PREMISES BEING LOT NO. _____

159th

HOUSE NO. _____

2240

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

M. L. L. Co.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.