Nº 11431

REMARKS ___

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	2/13/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	23' From up stream MH
HOUSE NO.	662		20 1.311
SIZE OF PIPE USED	. 6"		
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	P Glick
SHOW BY DIAGRAM RELATION (OF LATERAL TO WALL OF I	BUILDING SERVED.	. 4
		_	8'dp
SIGNED BILL Pappo	Inspector for City	FILED AT ENGINEER'S	OFFICE

Nº 11431

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON,	OHIO,	2/18.2	20
RECEIVED OF AGU	ck)		FEE OF \$	5
FOR WHICH PERMISSION IS GRANTED				
TO TAP JALLANDE	SEWER ON THE	<u></u>	art.	
of Washendry St A	AVE.) STATYPE OF STREET	ax	indult	
THE PREMISES BEING LOT NO.	180 (24)	_, HOUSE NO	662	
	,			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	NO. 19.1971 DULY PAS	SED BY THE CITY CO	UNCIL, AND RULES OF T	HE
DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR / A / A / A / A / A / A / A / A / A /	<u> </u>	· · · · · · · · · · · · · ·	•	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.