


N^o 11432

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 2/14/02 IF SO, HOW AND LOCATION FROM 231'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 125
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Buckeye Wrecking

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11432

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/12

RECEIVED OF Buckeye Wrecking

FEE OF \$ 45

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE South

OF Cherry Rd (NW)

AVE.

ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 4

, HOUSE NO. 125

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Buckeye

**Note: This permit covers work outside of building only. Any work in
of building is subject to Massillon Board of Health regulations.**