


Nº 11434

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2/19/02 IF SO, HOW AND LOCATION FROM 49' up Stream M/H
FIRST MANHOLE DOWN STREAM
HOUSE NO. 3161
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR T/S

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED *Jeffrey M. By* FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

N^o 11434

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/19, 2015

RECEIVED OF T & S

FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary SEWER ON THE South S

OF Lincoln W W

AVE.

ST. TYPE OF STREET: asphalt

THE PREMISES BEING LOT NO. ~~211~~ 16268

HOUSE NO: 3161

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR T & S

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.