Nº 11436

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/12/02	IF SO, HOW AND LOCATION FROM	79'					
HOUSE NO.	1260	FIRST MANHOLE DOWN STREAM	7.3					
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT						
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH						
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	, Bontrager					
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.								
			1260 Lonedale 127 -3' -8' 45' -3'					
SIGNED BITT Pappa	Inspector for City	G	R'S OFFICE					

Nº 11436

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	1	MASS	ILLON, OHIO,		28_
RECEIVED OF	Bout	tuger		FEE OF \$	5
FOR WHICH PERMISSION IS GF	RANTED				
TO TAP CUTOFF	whong late of	SEWER ON THE	HE	<u>last</u> weathers	
THE PREMISES BEING LOT NO.		-1	, HOUSE NO	126	<u> </u>
WORK TO BE DONE IN ACCORE DEPARTMENT OF PUBLIC SERV		NCE NO. 19.1971 DUI	LY PASSED BY THE CI	TY COUNCIL, AND RULES	S OF THE
NAME OF CONTRACTOR	-Effic	ient Ho	ner	A Section of the sect	in in

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.