


Nº 11437

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 3/13/02 IF SO, HOW AND LOCATION FROM 198'
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 1290
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Bontrager
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11437

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/28, 2020

RECEIVED OF Bontrager

FEE OF \$ 52

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Santa Ana SEWER ON THE East S

OF Asphalt AVE. Asphalt

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 16136

, HOUSE NO. 1290

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Efficient Homes

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.