


Nº 11438

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/4/02 IF SO, HOW AND LOCATION FROM 155'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1320
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR John's Exc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11438

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 03/01/02 20

RECEIVED OF _____ FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED John's Excavating

REPAIR TO TAP tap sanitary SEWER ON THE East CUTOFF _____ S

OF Lanedale Street NW ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16135 HOUSE NO. 16135/320

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR John's Excavating

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.