Nº 11442

REMARKS

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO	DATE INSPECTED	3/13/02	IF SO, HOW AND LOCATION FROM	107'
SIZE OF PIPE USED	HOUSE NO.	2290	FIRST MANHOLE DOWN STREAM	. 107
WAS LATERAL AT CURB? WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 2290 Bowling Green 7'dp +8'- 25'- 8'dp -22'		6"		
WAS ATTACHED TO MAIN	WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
2290 Bowling Green 7'dp - 8'- 25'- 8'dp22"		yes	NAME OF CONTRACTOR	Malavite
25'- 8'dp -22'	SHOW BY DIAGRAM RELATION	I OF LATERAL TO WALL OF	BUILDING SERVED.	1
25'- 8'dp - 22'				2290 Bowling Green
8'dp - 22" g 107'			← <u></u>	7'dp +8'-
i2.1/ P. 20-4				25'-
12.11 Page				8'dp22"
12.11 Pages		•	g	307'
SIGNED 12112 7 973 1 Inspector for City	SIGNED BILL Pappa		FILED AT ENGINEER'	S OFFICE

Nº 11442

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, O)HIO,	3/420_
RECEIVED OF	laute	FEE OF	\$
FOR WHICH PERMISSION IS GRANTED			
REPAIR TO TAP CUTOFF A T T T T T T T T T T T T	<i>d</i> .	Puet	s
DF Muleya Kheen All	AVE. C. T ST TYPE OF STREET	and al	market -
THE PREMISES BEING LOT NO.	1620	HOUSE NO.	290
WORK TO BE DONE IN ACCORDANCE WITH ORDINAN	ICE NO. 19.1971 DULY PASSE	ED BY THE CITY COUNCIL, AND	RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	1		The state of the s
NAME OF CONTRACTOR JUSTIA	guirled H	mes	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.