Nº 11443

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/12/02	IF SO, HOW AND LOCATION FROM	98'					
HOUSE NO.	2610	FIRST MANHOLE DOWN STREAM						
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT						
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH						
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Tissot					
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.								
		V	2510 Lindo Lone					
SIGNED Jolly	Inspector for City	FILED AT ENGINEER'S	OFFICE					

Nº 11443

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERN	ЛТ	TO	TAP	SEWER
T T/T/				

	Λ.	MASSILLON, OHIO,	3/6,20_
RECEIVED OF	- Verent	S. January	FEE OF \$
FOR WHICH PERMISSION IS	GRANTED		
TO TAP CUTOFF CU	AVE. ST. TYPE	ON THE	glato
WORK TO BE DONE IN ACCO DEPARTMENT OF PUBLIC SE	RDANCE WITH ORDINANCE NO. 19.19	71 DULY PASSED BY THE CITY CO	DUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	Karman		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.