



Nº 11447

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 3/28/02 IF SO, HOW AND LOCATION FROM 96'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 309-311
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Eslich

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Jeffrey M. King FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11447

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/12, 2015

RECEIVED OF Eslich

FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

Sanitary SEWER ON THE Wheat S

AVE.

OF 121st

ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 10

, HOUSE NO. 309-311

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Eslich

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.