## Nº 11449

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	4/4/02	— IF SO, HOW AND LOCATION FROM Topped into MH					
HOUSE NO	2315	FIRST MANHOLE DOWN STREAM					
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT					
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH					
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR Romans Pluming					
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.							
Not to scole SIGNED BITTUP	pas	2315 Rio Grende  -6'-  5'dp					
·	Inspector for City						

## Nº 11449

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	Kondut	MASSILLON, OHIO, —	FE	
OR WHICH PERMISSION IS GRANT	≣D			
O TAP	La Maria SEV	VER ON THE		1-1/2
CUTOFF (1) CYLAZA	AVE. ST. PY	, PE OF STREET	axin ( )	pt-
HE PREMISES BEING LOT NO	159	//), HOUSE	NO	2315
VORK TO BE DONE IN ACCORDANC DEPARTMENT OF PUBLIC SERVICE.	E WITH ORDINANCE NO. 1	9.1971 DULY PASSED BY T	HE CITY COUNCIL,	AND RULES OF THE
IAME OF CONTRACTOR	P151	ict »		ame Seg. :

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.