## Nº 11451

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	4/11/02	_ IF SO, HOW AND LOCATION FROM	118'
HOUSE NO.	1885	FIRST MANHOLE DOWN STREAM	110
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	•
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Romans Plumbing
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF	F BUILDING SERVED.	John Carroll DR. S.E.  5'dp_16  12' 45  20'  13'dp 122'
SIGNED #	Inspector for City	e FILED AT ENGINEER'S	118'.

## Nº 11451

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, _	3// 1/20
RECEIVED OF THINKING	FEE OF \$ \(\frac{1}{2}\)
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER ON THE	West
OF AVE. ST. TYPE OF STREET	asolite
THE PREMISES BEING LOT NO. 15987, HOUSE	NO. 1585
, /	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY	THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.