


No 11458

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4/2/02 IF SO, HOW AND LOCATION FROM 105, 153 from curb
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1118
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Buckeye

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED *[Signature]* FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11458

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/18

RECEIVED OF Buckeye FEE OF \$ 1

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP _____ SEWER ON THE _____
CUTOFF _____

OF Greenway AVE. North
ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. 9569, HOUSE NO. 1118

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Buckeye

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**

RH me