## Nº 11459

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	4/2/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	108'
HOUSE NO.	370	PHS I MANHOLE DOWN STREAM	- Lambaran
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	John's Exc.
SHOW BY DIAGRAM RELATION	N OF LATERAL TO WALL OF B	UILDING SERVED.  370 Show Ave Ne	5'-)45' - 36'
Not to scole		o108'	45
SIGNED BILL PAPE	Inspector for City	FILED AT ENGINEER'S OFFI	GE
REMARKS			

Nº 11459

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	<u> CA 18</u> ,20_
RECEIVED OF BOOK AND TO	alder 5	FEE OF \$
FOR WHICH PERMISSION IS GRANTED		*****
REPAIR TO TAP SEWI		
OF AVE. ST. TYP	É OF STREET	
THE PREMISES BEING LOT NO.	, HOUSE NO	ST 3710
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19. DEPARTMENT OF PUBLIC SERVICE.		,
NAME OF CONTRACTOR JOHN'S EV. CO	auting	is

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.