


Nº 11467

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4/01/02 IF SO, HOW AND LOCATION FROM ~~1121~~
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1121
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11467

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/27, 2025

RECEIVED OF Holderbaum

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE South

S

OF Woodland Ave.

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 10388-89

HOUSE NO. 1121

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Holderbaum

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.