Nº 11471

REMARKS ___

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/28/02	DISTANCE FROM FIRST MANHOLE DOWN STREAM CURB LINE AND DEPTH	185'		
HOUSE NO.	2163				
SIZE OF PIPE USED	6"				
WAS LATERAL AT CURB? _	yes				
WAS ATTACHED TO MAIN _	yes	NAME OF CONTRACTOR	H&W		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 53 Wye* C/O 6" Wye*					
		N L	2163 University 185'		
SIGNED W	Inspector for City	FILED AT ENGINEER'S	OFFICE		

Nº 11471

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	4/120_
RECEIVED OF A TU	FEE OF	·s57
Ç О́Я WHICH PERMIȘSION IS GRANTED		
REPAIR O TAP SEWE	ER ON THE ALL ALLA LULLAT	
of Much life Concernsor The	EDER HEET WAS ARREST	14 m
THE PREMISES BEING LOT NO. 159	9 HOUSE NO.	163
NORK TO BE DONE IN AGGODDANGE WITH ODDINANCE NO. 46.	ACTA DULV DAGGED DV THE CITY COLUMN. AND	
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19. DEPARTMENT OF PUBLIC SERVICE.	1971 DOLY PASSED BY THE CITY COUNCIL, AND	HULES OF THE
VAME OF CONTRACTOR		
• (

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.