FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED | 3/28/02 | IF SO, HOW AND LOCATION FROM 185' | | | |
|---|--------------------|--|--|--|--|
| HOUSE NO. | 2167 | FIRST MANHOLE DOWN STREAM | | | |
| SIZE OF PIPE USED | 6" | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT | | | |
| WAS LATERAL AT CURB? | yes | CURB LINE AND DEPTH | | | |
| WAS ATTACHED TO MAIN | yes | H&W NAME OF CONTRACTOR | | | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | | | | | |
| | | 2167 University 185' - B" moin | | | |
| SIGNED M | Inspector for City | FILED AT ENGINEER'S OFFICE | | | |
| REMARKS | | | | | |

N° 11472

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | | MASSILLON, OHIO, | · · · · · · · · · · · · · · · · · · · | <u> 4,/201_</u> |
|---|-------------|------------------------------|--|-----------------|
| RECEIVED OF | AND | | FEE OF \$ | 51 |
| FOR WHICH PERMISSION IS GRAI | NTED | | | |
| REPAIR TO TAP | metaly si | EWER ON THE CAR COST OF | West | |
| CUTOFF-() OFOFOF | ty Walnussy | VEDOE STREET | malaspa | ut |
| THE PREMISES BEING LOT NO | 0 00 | 899, HOUSE NO. | _000 | 167 |
| WORK TO BE DONE IN ACCORDA DEPARTMENT OF PUBLIC SERVIC | | 19.1971 DULY PASSED BY THE (| CITY COUNCIL, AND FIU | LES OF THE |
| NAME OF CONTRACTOR | Toley | | <u>Langer of the second of the s</u> | |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.