REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	3/28/02	IF SO, HOW AND LOCATION FROM	299'			
HOUSE NO.	2137	FIRST MANHOLE DOWN STREAM				
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT				
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH				
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	H &W			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.						
			5" 5" 2137 University	299' — 8' mair		
SIGNED W	Inspector for City	FILED AT ENGINEER'S OF	FICE	D/S MH		

Nº 11476

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	7/1/	MASSILLON, OHIO,		***************************************	4/20_	_
RECEIVED OF	H&W	<u> </u>	<u> 4, 112</u> 7	FEE OF \$ _	5	1
OR WHICH PERMISSION IS GRAN	VTED					_
TO TAP	mitaly SEW	ER ON THE 2013	may LUL	ext_	·	S
of Mully	Lity Courseys	LOF STREET	i i calend	aralda	et	_
THE PREMISES BEING LOT NO	01899	, HOUSI	E NO	21:	37	
					f	
VORK TO BE DONE IN ACCORDAN	NCE WITH ORDINANCE NO. 19	.1971 DULY PASSED BY	THE CITY COU	NCIL, AND RUL	ES OF THE	
DEPARTMENT OF PUBLIC SERVICE	E			•		
NAME OF CONTRACTOR	Tolund		1	A		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.