

Nº 11483

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 5/14/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

128'

HOUSE NO. 2325

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes


NAME OF CONTRACTOR

Jerry's Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Not to scale



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11483

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 4/2, 2005

RECEIVED OF Jerry's Excavating FEE OF \$ 100.50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR TO TAP Sanitary SEWER ON THE West S
CUTOFF _____

OF Wright Hotel Dr AVE. ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15918, HOUSE NO. 2325/CR

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Jerry's

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.