## Nº 11498

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6/3/02  HOUSE NO. 1470  SIZE OF PIPE USED 6"	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	84'
WAS LATERAL AT CURB?	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.	Lourenbrook Lane NE 1470 5' from east side
SIGNED IM INSPECTOR City  REMARKS	FILED AT ENGINEEI	R'S OFFICE
TENTAL TITLE		

## Nº 11498

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

// MASSILLON, OHIO,	5/27
Activity to Carlo	EOF\$
FOR WHICH PERMISSION IS GRANTED / JULIANIES	
REPAIR TO TAP SEWER ON THE MARKET	t de
OF THE THE STREET	Cost-
THE PREMISES BEING LOT NO. $\frac{1}{2}$	<u> (50</u>
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, DEPARTMENT OF PUBLIC SERVICE.	AND RULES OF THE
NAME OF CONTRACTOR	
Note: This permit covers work outside of building only. Any	work inside

walls of building is subject to Massillon Board of Health regulations.