

Nº 11500

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 6/3/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

84'

HOUSE NO. 1480

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED

Jeffrey M. Ky

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11500

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/7/20

RECEIVED OF Sprengshell Condo Co FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Grubbill

REPAIR TO TAP Franklin SEWER ON THE North S

CUTOFF Franklin AVE. ST. TYPE OF STREET Asphalt

OF Franklin THE PREMISES BEING LOT NO. Pt 02 857, HOUSE NO. 1480

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Grubbill

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.