## $N^{\circ}$ 11505

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM129'
HOUSE NO. 1510	FINGT MANNOLE DOWN STREAM
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	Laurenbrack NE  36' from east side
	129'
SIGNED My Inspector for City	FILED AT ENGINEER'S OFFICE
DELLA DICO	

## Nº 11505

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	0 . MA	SSILLON, OHIO,	5/20_
RECEIVED OF	as reduce C	ado	FEE OF \$
FOR WHICH PERMISSION IS GRANTET	allale	ill	
REPAIR TO TAP	SEWER ON	VTHE	Table 12 March
OF TOMAN SEA	AVE ST, TYPE OF	STREET	1.3.6.4.24
THE PREMISES BEING LOT NO	P+0685	HOUSE NO	1 1510
WORK TO BE DONE IN AGOOD AND	/	/	
WORKTO BE DONE IN ACCORDANCE DEPARTMENT OF PUBLIC SERVICE.	WITH OHDINANCE NO. 19.1971 I	JULY PASSED BY THE CIT	Y COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	Middel	<u>(</u>	<u></u> .
	//		•

Note: This permit cover's work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.