## $N^{0}$ 11509

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	5/20/02	_ IF SO, HOW AND LOCATION FROM 126'	
HOUSE NO.	1535	FIRST MANHOLE DOWN STREAM	120
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Grabill
SHOW BY DIAGRAM RELATION	N OF LATERAL TO WALL OF	BUILDING SERVED. 0 126	32 <sup>1</sup> _c/o
NOT TO SCORE			1535 Lourenbrook
SIGNED Juffly M /h	Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS			

## $N^{\circ}$ 11509

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	7) 17		/	,-,
	MASS	SILLON, OHIO,		<b>,</b> 20
RECEIVED OF	Log is idelited &	Colland	FEE OF \$	1.
THEOLIVED OF				
FOR WHICH PERMISSION IS GRANTEI	- yay	luck.		<i>;</i>
REPAIR /			en esta est	
TO TAP	SEWER ON T	HE	A STATE OF THE STA	{
OF 4444	AVE) AVE OF ST	REET	Land James Comment	
. 0.3	Line Com	ا ا	1	
THE PREMISES BEING LOT NO	Frocos	, HOUSE NO	<u> </u>	<u> </u>
•	/		£	
WORK TO BE DONE IN ACCORDANCE	WITH ORDINANCE NO. 19.1971 DU	LY PASSED BY THE CITY	COUNCIL, AND RULES O	FTHE
DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR	Madriel		÷	
· ·	/	<u> </u>		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.