

N^o 11513

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7/1/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

117'

HOUSE NO. 1497

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 

117'

Not to scale



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11513

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/7, 2001

RECEIVED OF Springhill Cords FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Grubel

REPAIR TO TAP Sanitary SEWER ON THE South S
CUTOFF Tyler Mill Dr NE

OF Tyler Mill Dr NE AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. P+ 04857, HOUSE NO. 1497

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Grubel

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.