

N^o 11518

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 5/9/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 70'

HOUSE NO. 2965

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Not to scale



SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

N^o 11518

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

05/08/02

RECEIVED OF _____

FEE OF \$

5

FOR WHICH PERMISSION IS GRANTED _____

Tissot Excavating

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE

South

S

OF

Crest Circle NW

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

15171

, HOUSE NO.

2965

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Tissot

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**