

Nº 11523

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/27/02

IF SO, HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM ---

HOUSE NO. 2625

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH -----

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Murphy

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

See attached page.

Not to scale

SIGNED B. H. Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE -----

REMARKS -----

N<sup>o</sup> 11523

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, 5/21/20

RECEIVED OF Murphy Enterprises FEE OF \$ 100

FOR WHICH PERMISSION IS GRANTED \_\_\_\_\_

REPAIR TO TAP Sanitary SEWER ON THE South S  
CUTOFF Ohio State Ave

OF Ohio State Ave ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 01913, HOUSE NO. 2625

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Murphy

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**

N68°35'21"E  
94.75'

Ohio State Drive

EX 21G  
25-40psi

Gas Service  
2" Domestic Water

Sanitary  
Cleanout  
(100' O.C.)

Inv. = 1090.0  
6" San  
@ 2.08% Min.  
N02°38'19"E  
468.55'

