

Ohio State Drive



N68°35'21"E
94.75'

EX. 2.5
25-40psi

Gas Service

2" Domestic Water

6' 6" 149.5'



Nº 11524

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

No Inspection

SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

N^o 11524

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

5/24

RECEIVED OF _____

Esligh

FEE OF \$ _____

15

FOR WHICH PERMISSION IS GRANTED _____

Reynolds - Hyde Bldg

REPAIR
TO TAP
CUTOFF

Shurbutt Ave.

SEWER ON THE _____

East

SI

OF _____

AVE.

ST. TYPE OF STREET _____

Academy

THE PREMISES BEING LOT NO. _____

06560

, HOUSE NO. _____

3000

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Esligh

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.