Nº 11527

REMARKS _

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5/30/02 HOUSE NO. 335	IF SO, HOW AND LOCATION FROM 52' FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	Glick NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	ı	6'dp
Not to scale		22' MH Is behind curb.
SIGNED My Inspector for City	FILED AT ENGINEER'S OFFICE	

	- •
Nº 11527 OFFICE OF THE DIRECTOR OF PUBLIC S	ERVI
PERMIT TO TAP SEWER	j
/ MASSILLON, OHIO,	_ کم <u>ح</u>
RECEIVED OF CHUN CLCA FEE OF \$	_5
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER ON THE USE OF THE	· · ·
OF	4
THE PREMISES BEING LOT NO. $\frac{1}{93}$, House No. $\frac{335}{1}$	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULE	S OF THE
DEPARTMENT OF PUBLIC SERVICE.	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.

NAME OF CONTRACTOR