

N^o 11528

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/18/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 36' from up stream mh

HOUSE NO. 769

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Cottrill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Not to scale



SIGNED Bill Pappas Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11528

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/31/20

RECEIVED OF Cathriel

FEE OF \$ 15

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

SEWER ON THE west

S

OF Franklin St

AVE.
ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 5157

HOUSE NO. 769

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Cathriel

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**